

## Operating Instructions Upgraded Auxiliary Heater (Parking Heater) for Parking Preheating Audi Q7 with Comfort Automatic Air-Conditioning

You can retrieve all necessary information and safety instructions to ensure flawless operation of your Upgraded Auxiliary Heater from the vehicle logbook's parking heater and ventilation - warm and cold - chapter.

	Please note that after servicing, settings of the upgrade may get lost.
	To reactivate the parking heater function, another coding of the vehicle components using the VCDS diagnosis system (VAG.COM) may be necessary.
$\bigcup$	The coding is carried out by Webasto installation partners. The execution of the new coding can possibly incur additional costs.

- We recommend matching the heating time to the driving time.
  - The following rule of thumb applies: driving time = heating time.

    Example: for a driving time of 20 min., the parking heating time is not to exceed 20 min.

    The T91 hand-held transmitter (see illustration) for the upgraded auxiliary heater differs in its design and function (no parking ventilation) from the hand-held transmitter of the standard parking heater.
- The preselection of the parking heating time and duration using the driver information system is not available.
- After services, it is possible that the coding of the upgrade has been reset. Please proceed as follows: ensure that the auxiliary heater is fully functional, prior to starting work.
   Coding of control units J255 and J364 via guided functions using the VAS tester 5051/5052:
  - 1. Read and write down coding value
  - 2. Coding using direct input for control unit J364 is possible from 0001 to 0002
  - 3. Attach the new coding to the vehicle documents.



Telestart T91 hand-held transmitter
The photo shows the black version

Webasto Thermo & Comfort SE Postfach 1410 82199 Gilching Germany

www.webasto.com

Ident.-Nr. 1312704F\_EN ● 06/12 ● Subject to modifications and errors Printed in Germany ● Webasto Thermo & Comfort SE 2012